



SUGGESTION:

To achieve a comfortable experience throughout the process of finding seats, two methods should be applied. Firstly, a separate path should be designed for wheelchair occupants to move around the Café area. Either adding another row of space at one side of the wall

or expanding the current existing paths are good improvements. Secondly, the amount of tables and chairs that currently crowd the area should be decreased, thus more space would give more accessibility to the disabled or differently abled. Consideration of changing the height of chairs can also be applied to the future improvements.

